

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.

FIG. 1A




FIG. 1B

DEST	SELECT NAME
1234 TORRANCE BLVD. REDONDO BEACH, CA	
<input checked="" type="checkbox"/>	CURSOR POINT
<input type="checkbox"/>	MOBILE
<input checked="" type="checkbox"/>	TOKYO RESTAURANT

FIG. 1C

DEST	SELECT NAME
5a	1232 TORRANCE BLVD. REDONDO
5b	(310)540-1234
5e	JAPANESE
	5c 2.4mi
	5d
<input checked="" type="checkbox"/>	CURSOR POINT
<input type="checkbox"/>	MOBILE
<input checked="" type="checkbox"/>	TOKYO RESTAURANT

FIG. 2A




FIG. 2B




FIG. 3




FIG. 4





FIG. 5

(A)

COORDINATES (LONGITUDE, LATITUDE)	POI ICON CODE	BORDERING ROAD NAME	LINK (NODE N ₁ , N ₂)	CATEGORY	
(x ₁ , y ₁)		ABC AVE.	RESTAU- RANT	BBB RESTAU- RANT
.....

(B)




FIG. 6




FIG. 7

7 / 11




FIG. 8




FIG. 9




FIG. 10




FIG. 11

